

27. Cassette tape cannot be eject.

INSPECTION PROCEDURE

1 Check if ACC or DOME fuse is OK?

NG

Replace fuse.

OK

2 Check the radio receiver assembly.

PREPARATION:

Disconnect the radio receiver assembly connector.

CHECK:

Check voltage terminals +B.

OK:

+B: 10 – 14 V

CHECK:

Check voltage terminal ACC when turn ignition switch ACC or ON position.

OK:

ACC: 10 – 14 V

CHECK:

Check continuity terminal GND.

OK:

GND: Continuity

NG

Replace or repair wire harness.

HINT:

When sending it for repair, leave as it is without attempting to take it out by force.

OK

Replace the radio receiver assembly.