

31. Power coming in, but DVD auto changer not operating

INSPECTION PROCEDURE

1 Is DVD inserted with correct side up?

NO

Insert correctly.

YES

2 Function OK if different DVD magazine inserted?

YES

DVD magazine faulty.

NO

3 Is radio operating normally?

YES

Go to step 7.

NO

4 Does continuity exist in speaker wire harness?

NO

Speaker wire harness faulty.

YES

5	Temporarily install another speaker. Function OK?
----------	--

YES**Speaker faulty.****NO**

6	Hiss noise from speaker?
----------	---------------------------------

NO**Power amplifier faulty.
Recheck system after repair.****YES****Radio assembly faulty. Recheck system after repair.**

7	Is temperature inside cabin hot?
----------	---

YES**Protective circuit in operation.****NO**

8	Has sudden temperature change?
----------	---------------------------------------

YES**Formation of condensation due to temp.
changes.****NO****DVD auto changer faulty.**