

Knock Control Module Monitor Description

MONITOR SUMMARY

If the ECM detects a malfunction in the engine—knock counter module, the ECM will illuminate the malfunction indicator lamp (MIL) and set DTC P1605.

RELATED DTC

Related DTCs	P1605	Knock counter module malfunction
--------------	-------	----------------------------------

MODEL YEAR CHART

Model Year	See Page
1996 to 1998	Ce-86