


## **COWL TOP SIDE PANEL (ASSY)**


## REMOVAL (With the cowl top to apron brace and front body pillar lower gusset removed.)








## INSTALLATION





in.
0.39 0.79 1.57