






G1	Airbag Sensor Assembly
G2	Mayday Battery
G3	Combination Meter Assembly
G4	Turn Signal Flasher Assembly
G5	VSC Off Switch
G6	Outer Mirror Switch Assembly
G8	Light Control Rheostat
G9	Center Differential Lock Switch
G12	A/C Amplifier Assembly
G13	A/C Amplifier Assembly
G14	Front Blower with Fan Motor Sub-Assembly
G15	Intake Air Temperature Sensor
G16	Glove Box Light
G17	Interior Foot Light RH
G18	Interior Foot Light LH
G19	Lower No. 1 Instrument Panel Airbag Assembly
G20	Lower No. 2 Instrument Panel Airbag Assembly
G21	Steering Sensor
G22	No. 1 Clearance Warning Buzzer
G23	Steering Lock Actuator Assembly
G24	Engine Switch
G25	ID Code Box
G26	Certification ECU Assembly
G27	Certification ECU Assembly
G28	Spiral Cable Sub-Assembly
G29	Spiral Cable Sub-Assembly
G30	Spiral Cable Sub-Assembly , Steering Wheel Heater Control Assembly
G31	Headlight Dimmer Switch Assembly
G32	Shift Lock Control ECU Sub-Assembly
G33	Multiplex Tilt & Telescopic ECU
G34	Seat Belt Control ECU
G35	Seat Belt Control ECU
G36	Transmission Control Switch
G37	DLC3
G38	Power Management Control ECU
G39	Power Management Control ECU
G40	Yaw Rate Sensor Assembly
G41	Four Wheel Drive Control ECU
G42	Four Wheel Drive Control ECU
G43	Driving Support ECU Assembly
G44	ECM
G45	ECM
G46	Main Body ECU
G106	ECM
G107	ECM


Position of Parts in Instrument Panel (Before Aug. 2013 Production)




90980-12391




90980-12366




90980-12557




90980-10799




90980-12368




90980-12423




90980-12550




90980-12368




90980-12554







90980-12557




90980-11667




90980-11918




90980-12452




90980-12452




90980-11986



90980-10825




90980-12092




90980-12370


Position of Parts in Instrument Panel (Before Aug. 2013 Production)




90980-12558




90980-12564




90980-12404




90980-12552




90980-12160




90980-10795




90980-12460




90980-12552




90980-11973




90980-11527




90980-12551




90980-12551



90980-11978










90980-12843




90980-12844


Position of Parts in Instrument Panel (Before Aug. 2013 Production)



Position of Parts in Instrument Panel (Before Aug. 2013 Production)



82824-26110



82824-26120