
























- A 4 High Pitched Horn Assembly
- A 5 Low Pitched Horn Assembly
- A 6 Front Airbag Sensor RH
- A 7 Front Airbag Sensor LH
- A 9 Condenser Blower Motor Assembly
- A 13 A/C Pressure Sensor
- A 16 Windshield Washer Motor and Pump Assembly
- A 19 Security Horn Assembly
- A 22 Windshield Wiper Motor Assembly
- A 23 Front Wiper Deicer (Windshield Glass)
- A 24 Skid Control ECU with Actuator Assembly
- A 25 Skid Control ECU with Actuator Assembly
- A 26 Brake Fluid Level Warning Switch (Brake Master Cylinder Reservoir Assembly)
- A 32 Noise Filter
- A 34 Junction Connector
- A 37 Junction Connector
- A 38 ECM
- A 45 Exhaust Gas Sensor
- A 49 Short Connector
- A 50 Short Connector
- A 64 Headlight ECU Sub-Assembly LH
- A 65 Headlight ECU Sub-Assembly RH
- A 67 Millimeter Wave Radar Sensor Assembly
- A 68 Headlight Cleaner Motor and Pump Assembly
- A 69 Wireless Door Lock Buzzer
- A 71 Hood Lock Assembly
- A 76 Junction Connector
- A 82 Heated Windshield Defroster (Windshield Glass)
- A 83 Heated Windshield Defroster (Windshield Glass)
- A 84 Heated Windshield Defroster (Windshield Glass)
- A 88 Front Tire Pressure Warning Antenna
- A 89 Cooler (Ambient Temperature Sensor) Thermistor

Position of Parts in Engine Compartment <LHD 3UR-FE From Sep. 2015 Production>




Position of Parts in Engine Compartment <LHD 3UR-FE From Sep. 2015 Production>


A 64
Gray



A 65
Gray




A 67
Black



A 68
Black




A 69
Gray




A 71
Black



A 76
Black




A 82
Black



A 83
Gray



A 84
Gray



A 88
Gray



A 89
Black

