













* 1 : w/ No. 1 EGR Valve Assembly
* 3 : Shielded





Cruise Control <1VD-FTV w/o DPF, From Sep. 2015 Production>, ECT and A/T Indicator <1VD-FTV w/o DPF, From Sep. 2015 Production>, Engine Control <1VD-FTV w/o DPF, From Sep. 2015 Production>





























A 24
Black




A 27
Black



A 31
Black



A 37
Blue




A 49
Gray




A 50
Gray




A 70
Gray




A 75
Gray




A 76
Black










































A 85
Black















A 86
Black














CA3
White




CA4
White





CA6
White



Cp1
Gray





EA1
White




EA2

White


Gray



EA3
White



EA4
White



EV1
Black

