












* 7 : Before Aug. 2017 Production
 * 8 : From Aug. 2017 Production




E117(A), E118(B)
Main Body ECU







E117(A), E118(B)
Main Body ECU




E117(A), E118(B)
Main Body ECU

A38(A), A85(B), A86(C), A87(D),
C53(E), C54(F), C110(G), C138(H)
ECM






A 24
Black




A 38
Black




A 49
Gray



A 50
Gray




A 74
White




A 75
Gray




A 85
Black




A 86
Black




A 87
Black




C 19
Gray



C 52
Blue




C 53
Black




Remote Control Mirror <From Sep. 2015 Production>


C110
Black




C138
Black




E117
White




E118
White




E148
Gray




E158
White




E160
Black




E161
White




E162
Black




I 11
White




I 22
White




I 33
White




I 35
White




I 37
White




I 38
White



I 40
White



I 41
White




K 2
White




L 1
White




m 1
White




m 4
White




2H
White





21
White





2J
White



CA3
White





CA4
White





EA1

White




EA3

White




EA4

White




EK2


White




EL1
White




IE1
Gray




IE2
Blue




IE3
White




IE4
Gray



IE5
Blue



IE6
White



Im1
White

