

* 8:Before Nov. 2017 Production
* 9:From Nov. 2017 Production
* 12:w/ Pre-Collision System
* 13:w/o Pre-Collision System

W1 Visor Assembly RH
W2 Vanity Light Assembly RH
W3 Map Light Assembly
W4 Map Light Assembly
W5 Sliding Roof Control ECU (Sliding Roof Drive Gear Sub-Assembly)
W6 Inner Rear View Mirror Assembly
W7 Rain Sensor
W9 Lane Departure Warning Camera
W10 No. 1 Room Light Assembly
W11 Visor Assembly LH
W12 Vanity Light Assembly LH
W13 No. 11 Junction Connector
W14 Telephone Microphone Assembly
W16 Forward Recognition with Heater Hood Sub-Assembly
W17 No. 13 Junction Connector
W18 Forward Recognition Camera

X1 Rear No. 1 Ultrasonic Sensor RH
X2 Rear No. 1 Ultrasonic Sensor Center RH
X3 Rear No. 1 Ultrasonic Sensor LH
X4 Rear No. 1 Ultrasonic Sensor Center LH

Y1 Rear Window Defogger (Back Window Glass)
Y2 Glass Breakage Sensor (Back Window Glass)

k1 Rear Height Control Sensor Sub-Assembly LH

z22 Rear Television Camera Assembly

W1
White



90980-12322

W2
Gray



W3
White



90980-12554

W4
White



90980-12460

W5
White



90980-12812

W6
White



90980-12368
(Before Nov. 2017 Production)

W6
Black



90980-12368
(From Nov. 2017 Production)

W7
Black



82824-50130

W9
Gray



90980-12552

W10
White



90980-12366

W11
White



90980-12322

W12
Gray



W13
White



90980-12737

W14
White



90980-12366

W16
White



90980-12063

W17
White



90980-12737

W18
Gray



90980-12552

X1
Black



90980-11246

X2
Black



90980-11246

X3
Black



90980-11246

X4
Black



90980-11246

Y1
White

90980-10913

Y2
Black



86146-33010

k1
Black



90980-12353

z22
Black



90980-12A59