

* 10:Before Nov. 2017 Production
* 11:From Nov. 2017 Production
* 12:w/ Pre-Collision System
* 13:w/o Pre-Collision System

W1	Visor Assembly RH
W2	Vanity Light Assembly RH
W3	Map Light Assembly
W4	Map Light Assembly
W5	Sliding Roof Control ECU (Sliding Roof Drive Gear Sub-Assembly)
W6	Inner Rear View Mirror Assembly
W7	Rain Sensor
W9	Lane Departure Warning Camera
W10	No. 1 Room Light Assembly
W11	Visor Assembly LH
W12	Vanity Light Assembly LH
W13	No. 11 Junction Connector
W14	Telephone Microphone Assembly
W16	Forward Recognition with Heater Hood Sub-Assembly
W17	No. 13 Junction Connector
W18	Forward Recognition Camera
X1	Rear No. 1 Ultrasonic Sensor RH
X2	Rear No. 1 Ultrasonic Sensor Center RH
X3	Rear No. 1 Ultrasonic Sensor LH
X4	Rear No. 1 Ultrasonic Sensor Center LH
Y1	Rear Window Defogger (Back Window Glass)
Y2	Glass Breakage Sensor (Back Window Glass)
k1	Rear Height Control Sensor Sub-Assembly LH
z22	Rear Television Camera Assembly

W1
White



90980-12322

W2
Gray



W3
White



90980-12554

W4
White



90980-12460

W5
White



90980-12812

W6
White



90980-12368
(Before Nov. 2017 Production)

W6
Black



90980-12368
(From Nov. 2017 Production)

W7
Black



82824-50130

W9
Gray



90980-12552

W10
White



90980-12366

W11
White



90980-12322

W12
Gray



W13
White



90980-12737

W14
White



90980-12366

W16
White



90980-12063

W17
White



90980-12737

W18
Gray



90980-12552

X1
Black



90980-11246

X2
Black



90980-11246

X3
Black



90980-11246

X4
Black



90980-11246

Y1
White

90980-10913

Y2
Black



86146-33010

k1
Black



90980-12353

z22
Black



90980-12A59