
LUGGAGE COMPARTMENT DOOR GARNISH SUB–ASSY OUTSIDE

760BX–03

REPLACEMENT

1. REMOVE LUGGAGE COMPARTMENT DOOR COVER

(a) Remove the 15 clips and luggage compartment door cover.



2. REMOVE LUGGAGE COMPARTMENT DOOR GARNISH SUB–ASSY OUTSIDE

(a) Remove the 4 screws.

(b) Using a screwdriver, remove the luggage compartment door garnish outside.

HINT:

Tape the screwdriver tip before use.