




H 1 Speaker (Front Door RH)
H 3 Outer Rear View Mirror (RH)
H 4 Power Window Regulator Motor (Front RH)
H 6 Power Window SW (Front RH)
H 7 Courtesy Lamp (Front Door RH)
H 8 Door Lock Assembly (Front RH)
H 11 Outer Rear View Mirror (RH)
H 11 Outer Rear View Mirror (RH)
H 12 Power Window Regulator Motor (Front RH)
H 13 Power Window SW (Front RH)

I 1 Speaker (Front Door LH)
I 2 Outer Rear View Mirror (LH)
I 5 Power Window Regulator Motor (Front LH)
I 6 Courtesy Lamp (Front Door LH)
I 7 Door Lock Assembly (Front LH)
I 10 Outer Rear View Mirror (LH)
I 10 Outer Rear View Mirror (LH)

J 1 Power Window SW (Rear RH)
J 3 Power Window Regulator Motor (Rear RH)
J 5 Door Lock Assembly (Rear RH)
J 6 Power Window SW (Rear RH)
J 7 Power Window Regulator Motor (Rear RH)








K 1 Power Window SW (Rear LH)
K 3 Power Window Regulator Motor (Rear LH)
K 5 Door Lock Assembly (Rear LH)
K 6 Power Window SW (Rear LH)
K 7 Power Window Regulator Motor (Rear LH)

M 1 Power Window Master SW
M 2 Power Window Master SW


f 1 Speed Sensor (Rear RH)

g 1 Speed Sensor (Rear LH)







Position of Parts in Body <LHD>




(From Aug. 2010 Production)






(From Jan. 2009 Production until Aug. 2010 Production)



(From Jan. 2009 Production until Aug. 2010 Production)




(From Aug. 2010 Production)



Position of Parts in Body <LHD>


J 6

White




J 7

White




K 1

White




K 3

White




K 5

White




K 6

White




K 7

White




M 1

White



M 2

White



f 1

White



g 1

White

