



Mirror Heater , Rear Window Defogger




Mirror Heater , Rear Window Defogger

- * 1 : Except *2
- * 2 : Turkey, Russian
- * 3 : Before Jan. 2009 Production
- * 4 : From Jan. 2009 Production until Aug. 2010 Production
- * 5 : From Aug. 2010 Production




Mirror Heater , Rear Window Defogger


A 41
White




A 42
White




E 38
White




E 49
Black




F 16
Gray




H 3
White



H 11
White




H 11
White




(From Aug. 2010 Production)

(From Jan. 2009 Production until Aug. 2010 Production)


I 2
White



I 10
White




I 10
White



(From Aug. 2010 Production)

(From Jan. 2009 Production until Aug. 2010 Production)

N 18
Black



N 19
Black




N 22
White




P 1
Black




3D
Gray




3L
Gray




3M
White



3S
White



3U
White
















IB
White




(RHD)


Mirror Heater , Rear Window Defogger



EA1
White



HE2
White



IE2
White

