











\* 1 : w/ Blind Spot Monitor System  
\* 2 : w/o Blind Spot Monitor System





I86(A), I87(B), O2(C)  
Certification ECU









































A 15

Gray




A 33

White




A 39

Gray



A 71

Gray




A 73

Gray




E 11

Gray




I 3

Gray




I 4

Gray




I 12

White




I 13

White




I 17

Black




I 18

Black




I 24

Black




I 42



















White





I 46

White












IA8  
Gray




IN1  
White




IO1  
White




IO2  
White




IS1  
White




Ic1  
White




JI1  
Gray



JI2  
Blue



KI1  
White



KI2  
White

