











Position of Parts in Instrument Panel <RHD>




- A 1 Turn Signal Lamp (Front RH)
- A 2 Inlet Air Temp. Sensor (Air Cleaner)
- A 3 Air Flow Meter
- A 4 A/C Pressure Sensor No.1
- A 5 Pressure SW
- A 6 Clearance Lamp (Front RH)
- A 7 Headlamp (RH)
- A 8 Headlamp Leveling Motor (RH)
- A 9 Brake Vacuum Warning SW
- A 10 Brake Fluid Level Warning SW
- A 11 Windshield Wiper Motor
- A 12 Airbag Sensor (Front RH)
- A 13 Airbag Sensor (Front LH)
- A 14 Ambient Temp. Sensor
- A 15 Horn (Low)
- A 16 Horn (High)
- A 17 Windshield Washer Motor
- A 18 Rear Washer Motor
- A 19 Headlamp (LH)
- A 20 Headlamp Leveling Motor (LH)
- A 21 Clearance Lamp (Front LH)
- A 23 Turn Signal Lamp (Front LH)
- A 24 Short Pin (Vacuum)
- A 28 Magnet Valve
- A 29 Daytime Running Light (Headlamp Assembly RH)

Position of Parts in Instrument Panel <RHD>



(Before Jan. 2017 Production)



(Before Dec. 2013 Production)



(From Dec. 2013 Production)

