





REAR FLOOR No. 3 CROSSMEMBER (ASSY)**REMOVAL (With the rear floor pan removed.)**

INSTALLATION

