




Audio System (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production),
 Navigation System (Radio & Display Receiver Assembly Type) (From Aug. 2013 until Aug. 2017 Production),
 Parking Assist (Rear View Monitor) (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production)



A horizontal number line with arrows at both ends. It has four major tick marks labeled 5, 6, 7, and 8. There are also two minor tick marks between 5 and 6, and between 6 and 7, dividing each of these intervals into three equal parts. This means the minor tick marks are at 5.5 and 6.5.




Audio System (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production),
 Navigation System (Radio & Display Receiver Assembly Type) (From Aug. 2013 until Aug. 2017 Production),
 Parking Assist (Rear View Monitor) (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production)




85 LAND CRUISER / LAND CRUISER PRADO (Cont'd)

(Cont. next page)

Audio System (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production),
 Navigation System (Radio & Display Receiver Assembly Type) (From Aug. 2013 until Aug. 2017 Production),
 Parking Assist (Rear View Monitor) (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production)




Audio System (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production),
 Navigation System (Radio & Display Receiver Assembly Type) (From Aug. 2013 until Aug. 2017 Production),
 Parking Assist (Rear View Monitor) (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production)



85 LAND CRUISER / LAND CRUISER PRADO (Cont'd)

(Cont. next page)


Audio System (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production),
 Navigation System (Radio & Display Receiver Assembly Type) (From Aug. 2013 until Aug. 2017 Production),
 Parking Assist (Rear View Monitor) (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production)



85 LAND CRUISER / LAND CRUISER PRADO (Cont'd)

Audio System (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production),
 Navigation System (Radio & Display Receiver Assembly Type) (From Aug. 2013 until Aug. 2017 Production),
 Parking Assist (Rear View Monitor) (Radio & Display Receiver Assembly Type w/ Stereo Component Amplifier Assembly) (From Aug. 2013 until Aug. 2017 Production)

LAND CRUISER / LAND CRUISER PRADO (EM27T3E)



- * 3 : w/ Glass Hatch Opener
- * 4 : w/o Glass Hatch Opener
- * 5 : w/ Multi-Terrain Monitor
- * 6 : w/o Multi-Terrain Monitor
- * 16 : Before Jun. 2015 Production
- * 17 : From Jun. 2015 Production
- * 18 : Australia
- * 19 : Except Australia