




Mirror Heater <Before Aug. 2015 Production> , Rear Window Defogger <Liftgate Type , Before Aug. 2015 Production>







A 34
White




E 35
White




E 36
White




E 60




E 66
White




E 69
Gray




E 81
White



F 10
White




F 28
White




F 64

White




F 77

White




F 79

White




I 17

White




I 15

White




I 32

White




I 35

White




S 14

Black




S 15

White




S 16

White




S 17

White




S 18

White




S 20

White




S 21

White




S 27

Dark Gray




2B

White




2D


White




AK1
Blue




EA1
White




FE4
White




IE2
Blue




IE3
White



IE5
Blue



IE6
White



SK1
White

