











Seat Belt Warning <Before Jan. 2013 Production, From Jan. 2013 Production until Aug. 2015 Production China>









- * 3 : w/ Multi-Display
- * 4 : w/o Multi-Display w/ Stereo Component Amplifier
- * 5 : w/o Multi-Display w/o Stereo Component Amplifier
- * 6 : Before Jul. 2009 Production
- * 7 : From Jul. 2009 Production until Jan. 2012 Production
- * 12 : Liftgate Type
- * 13 : Swing Type
- * 19 : From Jan. 2012 Production
- * 24 : Before Jan. 2012 Production Liftgate Type
- * 25 : From Jan. 2012 Production Liftgate Type, Swing Type
- * 26 : 1VD-FTV w/ DPF
- * 27 : 1VD-FTV w/o DPF
- * 28 : 3UR-FE, 1UR-FE
- * 30 : From Jan. 2012 Production Liftgate Type




A 24
Black




A 37
Blue




C 44
Blue




E 1
White




E 3
White




E 7
White




E 31
White




E 47
Yellow


































E 59



E 60









EA1



White





EA2

White


Gray



EA3
White




EE1
White




EK2

White



EK3

Black



EL1

White

