



Position of Parts in Engine Compartment <RHD>

- * 1: Before Jun. 2013 Production
- * 2: From Jun. 2013 Production
- * 5: Before Mar. 2017 Production
- * 6: From Mar. 2017 Production




- B 1 Inverter with Converter Assembly
- C 1 Fuel Injector Assembly No. 1
- C 2 Fuel Injector Assembly No. 2
- C 3 Fuel Injector Assembly No. 3
- C 4 Fuel Injector Assembly No. 4
- C 5 Ignition Coil No. 1
- C 6 Ignition Coil No. 2
- C 7 Ignition Coil No. 3
- C 8 Ignition Coil No. 4
- C 9 ECM
- C 11 Crank Position Sensor
- C 12 Throttle Body with Motor Assembly
- C 13 Cam Position Sensor
- C 14 E.F.I. Engine Coolant Temperature Sensor
- C 15 E.F.I. Vacuum Sensor Assembly
- C 16 Oxygen Sensor (Bank 1 Sensor 2)
- C 17 Air Fuel Ratio Sensor (Bank 1 Sensor 1)
- C 18 EGR Valve Assembly
- C 19 Purge VSV
- C 20 Camshaft Timing Oil Control Valve Assembly (Bank 1)
- C 21 Intake Mass Air Flow Meter Sub-Assembly
- C 22 Compressor with Motor Assembly
- C 23 Shift Lever Position Sensor
- C 24 Hybrid Vehicle Transaxle Assembly
- C 25 Hybrid Vehicle Transaxle Assembly
- C 26 Hybrid Vehicle Transaxle Assembly
- C 27 Engine Water Pump Assembly
- C 28 Inverter with Converter Assembly
- C 29 Crank Position Sensor
- C 30 E.F.I. Engine Coolant Temperature Sensor
- D 1 Compressor with Motor Assembly
- D 2 Inverter with Converter Assembly
- E 1 Knock Control Sensor (Bank 1)
- E 2 Engine Oil Pressure Switch Assembly
- L 1 Inverter with Converter Assembly
- W 1 Hybrid Vehicle Transaxle Assembly
- W 2 Inverter with Converter Assembly
- W 3 Hybrid Vehicle Transaxle Assembly
- W 4 Inverter with Converter Assembly
- W 5 Hybrid Vehicle Transaxle Assembly
- z 6 Cooling Fan ECU , Cooling Fan Motor

Position of Parts in Engine Compartment <RHD>




Position of Parts in Engine Compartment <RHD>


C 21
Black




C 22
Black




C 23
Gray




C 24
Black



C 25
Black




C 26
Black




C 27
Black



C 28
Black




C 29
Black




C 30
Black




D 1
Orange



D 2
White




E 1
Black




E 2
Gray




L 1
White




W 1
Orange




W 2
Orange



W 3
Orange



W 4
Orange



Position of Parts in Engine Compartment <RHD>

