




Ground Point




- * 6 : Before Jul. 2014 Production
- * 7 : From Jul. 2014 Production
- *11 : Before May 2015 Production
- *12 : From May 2015 Production
- *13 : w/ Pre-Crash Safety System
- *16 : From Jul. 2014 Production until May 2015 Production
- *19 : From Oct. 2016 Production
- *22 : LED Type Tail and Stop Light
- *30 : w/ Power Switch


Ground Point







Ground Point






- * 1 : w/ Entry Function
- * 2 : w/o Entry Function
- * 3 : w/ Double Locking
- * 6 : Before Jul. 2014 Production
- * 7 : From Jul. 2014 Production
- * 8 : w/ Tire Pressure Warning System
- * 9 : w/ Automatic Retractable Mirror
- *10 : w/o Automatic Retractable Mirror
- *11 : Before May 2015 Production
- *12 : From May 2015 Production
- *13 : w/ Pre-Crash Safety System
- *15 : w/ Automatic High Beam System
- *16 : From Jul. 2014 Production until May 2015 Production
- *20 : Before Mar. 2017 Production
- *21 : From Mar. 2017 Production
- *24 : Before May 2018 Production
- *25 : From May 2018 Production
- *26 : From Mar. 2017 Production until May 2018 Production
- *29 : w/o Power Switch
- *31 : w/ Seat Heater
- *39 : w/o Power Window







Ground Point




Ground Point




Ground Point




















Ground Point



- * 6 : Before Jul. 2014 Production
- * 7 : From Jul. 2014 Production
- *17 : w/ Rear Fog Light LH
- *18 : w/ Rear Fog Light RH
- *20 : Before Mar. 2017 Production
- *21 : From Mar. 2017 Production
- *22 : LED Type Tail and Stop Light
- *23 : Bulb Type Tail and Stop Light
- *28 : Radio & Display Receiver Assembly Type
- *43 : 8 Speaker







Ground Point

