



Position of Parts in Instrument Panel <RHD S/D>





A 13 Stop Lamp SW
A 13 Stop Lamp SW
A 16 Clutch Start SW
A 19 Power Steering ECU
A 19 Power Steering ECU
A 20 Accelerator Position Sensor
A 26 Junction Connector


E 1 Blower SW
E 2 A/C Thermistor No.1
E 3 Blower Resistor
E 4 Blower Motor
E 5 A/C SW
E 6 Rear Window Defogger SW
E 8 A/C Amplifier
E 8 A/C Amplifier
E 10 Junction Connector
E 18 Rear Window Defogger SW
E 18 Rear Window Defogger SW






(TMMF Made Before Nov. 2008 Production, TMC Made Except H/B From Aug. 2008 Production)








(TMC Made H/B From Aug. 2008 Production, TMMF Made From Nov. 2008 Production)




(TMC Made From Aug. 2007 Production, TMMF Made From Nov. 2008 Production)




(Except TMC Made From Aug. 2007 Production and TMMF Made From Nov. 2008 Production)





(TMMF Made, TMC Made H/B Before Aug. 2008 Production S/D Before Nov. 2006 Production)




(TMMF Made From Nov. 2008 Production, TMC Made H/B From Aug. 2008 Production, S/D From Aug. 2007 Production)



(TMMF Made Before Nov. 2008 Production, TMC Made H/B Before Aug. 2008 Production, S/D Before Aug. 2007 Production)



(S/D Before Aug. 2007 Production)



(S/D From Aug. 2007 Production)